

Troubleshooting guidelines for ICBA & Thermo coffee brewer

Coffee Crimes

Resolution

The filter holder is overflowing and no coffee is going into the air pot.	The filter spring is missing.
The coffee tastes bitter.	The filter paper was not removed after the brew was made.
The air pot overfills.	The old brew was left inside the pot before the new brew was made.
The coffee tastes cold.	The air pot lid was not replaced quickly enough. Or the air pots have not been pre-heated.
The coffee tastes stale.	Coffee has been sitting in the air pot for longer than two hours, or the coffee was opened too far in advance.
The regular coffee tastes like flavour coffee	The flavour filter basket was used to brew regular Brazil or coffee of the quarter tainting the taste.
